

BIL	Quotation Reference	Description	Advertisement Date	Closing Date (Not Later Than 2.00PM)	Quotation Fee	Requesting Department	Focal Person
3	BME/A2K/(962)/2022/HTD(A17)	<p><b>TO SERVICE AND REPAIR ONE (1) UNIT OF HIRAYAMA AUTOCLAVE, BME 26235, MODEL: HV 85, SN: 3042102370 AT VIROLOGY LAB, SUMBILING. (2022-3670)</b></p> <p><u>PLACE OF SUBMISSION:</u>            QUOTATION BOX (GROUND FLOOR)            MINISTRY OF HEALTH COMMONWEALTH DRIVE            BANDAR SERI BEGAWAN, BB 3910            NEGARA BRUNEI DARUSSALAM</p>	05/12/2022	17/12/2022	\$5.00	JABATAN TEKNOLOGI PENJAGAAN KESIHATAN, KEMENTERIAN KESIHATAN.	DK HANI MAHYANA BINTI PG HAJI DAMIT  JURUTERA PERUBATAN HAYAT  TEL: 2242424 ext 8693 (RIPASH)

## LAMPIRAN - A1

RUJ: BME/A2K/(962)/2022/HTD (A17)

22/11/2022

TO SERVICE AND REPAIR ONE (1) UNIT OF HIRAYAMA AUTOCLAVE, BME26235 , MODEL: HV 85, SN: 30421052370 AT VIROLOGY LAB, SUMBILING. (2022-3670)

### SCOPE OF WORK

BME26235  
SN: 30421035270  
MODEL: HV 85  
BRAND : HIRAYAMA

#### SKOP OF WORK:

1. PERFORM EXTERNAL AND INTERNAL CLEANING OF MACHINE.
2. REMOVE SPAREPARTS HEATER AND SENSOR PROBE.
3. INSTALL SPAREPARTS HEATER AND SENSOR PROBE.
4. UPDATE FIRMWARE FOR INSTALLED SPAREPARTS.
5. CALIBRATE HEATER AND SENSOR PROBE.
6. CALIBRATE EGO HEAT SENSOR.
7. PERFORM GENERAL CLEANING.
8. PERFORM FUNCTIONALITY TEST.

## LAMPIRAN - A2

RUJ: BME/A2K/(962)/2022/HTD (A17)

TO SERVICE AND REPAIR ONE (1) UNIT OF HIRAYAMA AUTOCLAVE, BME26235 , MODEL: HV 85, SN: 30421052370 AT VIROLOGY LAB, SUMBILING. (2022-3670)

NO	SPAREPART	PART NUMBER	QUANTITY
1	HEATER		1
2	SENSOR PROBE		1