

Rujukan Kami: (88) MOH/HQ/P/IKLAN-SH/2025

LAMPIRAN 3

BIL	Quotation Reference	Description	Advertisement Date	Closing Date (Not Later Than 09.00AM)	Quotation Fee	Requesting Department
3	BME/A2K/(1457)/2025/HTD (A17)	TO TROUBLESHOOT AND REPAIR OF BIOMERIEUX BLOOD CULTURE SYSTEM, MODEL: BACT/ALERT VIRTUO, SERIEL NO: VRTA-00100, BME16781 (2025-6462).	16/06/2025	05/07/2025	\$5.00	JABATAN TEKNOLOGI PENJAGAAN KESIHATAN, KEMENTERIAN KESIHATAN

LAMPIRAN - A1

RUJ: BME/A2K/(1457)/2025/HTD (A17)

3/6/2025

TO TROUBLESHOOT AND REPAIR OF BIOMERIEUX BLOOD CULTURE SYSTEM, MODEL: BACT / ALERT VIRTUO, SERIAL NO: VRTA-00100, BME NO: BME16781 (2025-6462)

SCOPE OF WORK

Equipment details

Description : BIOMERIEUX BLOOD CULTURE SYSTEM

Brand : BIOMERIEUX

Model : VIRTUO 3D

BME NO : BME16781

S/N : VRTA-00100

Part to be replaced:

- 1 - KIT VIRTUO MOTOR GRIPPER
- 2 - KIT VIRTUO FUSES, BLADE
- 3 - KIT VIRTUO CABLE ASSY Y AXIS DC POWER
- 4 - APC RBC117 REPLACEMENT BATTERY

Scope of work:

- To disconnect and dismantle the faulty parts ,
- To install the new parts
- To perform installation and operation verification
- To carry out system performance verification

LAMPIRAN - A2

RUJ: BME/A2K/(1457)/2025/HTD (A17)

TO TROUBLESHOOT AND REPAIR OF BIOMERIEUX BLOOD CULTURE SYSTEM, MODEL: BACT / ALERT VIRTUO, SERIAL NO: VRTA-00100, BME NO: BME16781 (2025-6462)

	SPAREPART	PART NUMBER	QUANTITY
1	TO TROUBLESHOOT AND REPAIR OF BIOMERIEUX BLOOD CULTURE		1
2	KIT VIRTUO MOTOR GRIPPER	6205153	1
3	KIT VIRTUO FUSES, BLADE	6202410	1
4	KIT VIRTUO CABLE ASSY Y AXIS DC POWER	6207601	1
5	APC RBC117 REPLACEMENT BATTERY		1