LAMPIRAN - A1

RUJ: BME/A2K/(1528)/2025/HTD (a17)

8/10/2025

TO SERVICE ONE OFF PPM THREE (3) UNITS OF TERUMO BCT AUTOMATED BLOOD COLLECTION SYSTEM, BME9430, BME9431, BME9432 AT BLOOD DONATION CENTRE, RIPAS HOSPITAL.

SCOPE OF WORK

- 1. To service and repair three units of automated blood collection system at BDC, RIPAS Hospital:
- a) One time preventive maintenance 3 lot BME9430 WO 2025-8072 , BME9431 WO 2025-8071 , BME9432 WO 2025-8073 General mechanical inspection and cleaning -
- * IV Pole
- * Display console
- * Display arm
- * Front panel valves
- * Pump rotor test
- * Door alignment
- * Door screws test
- * Inner Cabinet
- * General Inspection
- * Brake System
- * General Cleaning
- * Filler Latch Lubrication

Electrical Safety and Power Tests

- * Grounding Straps Test
- * Ground Wire Resistance Test
- * External Ethernet Isolation Test
- * Line Voltage Test
- * Power Up Test
- * Normal Condition with Neutral Closed
- * Single Fault Condition with Neutral Open

5V Tes

OVP, OTW and Reset Test

Fan Direction and Failure Tests

- * Air Flow Direction
- * Fan Failure Detection

Machine and Software Information

- * Machine On Time
- * Number of Runs
- * Trima Accel Software Version
- * Service Software Version

Trima Calibration

- * Cassette Plate Down Test
- * Trima Accel Calibration
- * Install Calibration Files

Verifications

- * Alarm LED Test
- * AGC Upper Level Sensor Air Test
- * AGC Lower Level Sensor Air Test
- * Touch Screen Test
- * Access Pressure Sensor Test
- * Centrifuge Pressure Sensor Test

Trima Accel Autotest

Pump Occlusion Tests

- * AC, Inlet & Return Pump Occlusion
- * Plasma & Platelet Pump Occlusion
- * Machine Set-Up
- 2. Replacement of spareparts and Disposal of any used spare parts, unless otherwise instructed.
- a) 704010003 Sensor, Level, TR/OP 3 ea b) 704310203 Return rotor washer 6 unit c) 80300 Trima Accel LRS Platelet, plasma set 3pcs
- 3. Work on the system is to be carried out by engineer(s) authorised in providing maintenance to the equipment.
- 4. Perform functional test, verification and performance check post-maintenance.
- 5. Apply preventive maintenance sticker/tag after successful service. All work are signed and documented.

LAMPIRAN - A2

RUJ: BME/A2K/(1528)/2025/HTD (a17)

TO SERVICE ONE OFF PPM THREE (3) UNITS OF TERUMO BCT AUTOMATED BLOOD COLLECTION SYSTEM, BME9430 , BME9431 , BME9432 AT BLOOD DONATION CENTRE, RIPAS HOSPITAL.

	SPAREPART	PART NUMBER	QUANTITY
1	ONE OFF PREVENTIVE MAINTENANCE		3
2	SENSOR, LEVEL, TR/OP	704010003	3
3.	RETURN ROTOR WASHER	704310203	6
4	TRIMA ACCEL LRS PLATELET, PLASMA SET	80300	3

LAMPIRAN - A1

RUJ: BME/A2K/(1528)/2025/HTD (a17)

8/10/2025

TO SERVICE ONE OFF PPM THREE (3) UNITS OF TERUMO BCT AUTOMATED BLOOD COLLECTION SYSTEM, BME9430 , BME9431 , BME9432 AT BLOOD DONATION CENTRE, RIPAS HOSPITAL.

SCOPE OF WORK

- 1. To service and repair three units of automated blood collection system at BDC, RIPAS Hospital:
- a) One time preventive maintenance 3 lot

BME9430 WO 2025-8072, BME9431 WO 2025-8071, BME9432 WO 2025-8073

General mechanical inspection and cleaning -

* IV Pole

3 3 1

- * Display console
- * Display arm
- * Front panel valves
- * Pump rotor test
- * Door alignment
- * Door screws test
- * Inner Cabinet
- * General Inspection
- * Brake System
- * General Cleaning
- * Filler Latch Lubrication

Electrical Safety and Power Tests

- * Grounding Straps Test
- * Ground Wire Resistance Test
- * External Ethernet Isolation Test
- * Line Voltage Test
- * Power Up Test
- * Normal Condition with Neutral Closed
- * Single Fault Condition with Neutral Open

5V Test

OVP, OTW and Reset Test

Fan Direction and Failure Tests

- * Air Flow Direction
- * Fan Failure Detection

Machine and Software Information

- * Machine On Time
- * Number of Runs
- * Trima Accel Software Version
- * Service Software Version

Trima Calibration

- * Cassette Plate Down Test
- * Trima Accel Calibration
- * Install Calibration Files

Verifications

- * Alarm LED Test
- * AGC Upper Level Sensor Air Test
- * AGC Lower Level Sensor Air Test
- * Touch Screen Test
- * Access Pressure Sensor Test
- 2. Replacement of spareparts and Disposal of any used spare parts, unless otherwise instructed.
- a) 704010003 Sensor, Level, TR/OP 3 ea
- b) 704310203 Return rotor washer 6 unit
- c) 80300 Trima Accel LRS Platelet, plasma set 3pcs
- 3. Work on the system is to be carried out by engineer(s) authorised in providing maintenance to the equipment.
- 4. Perform functional test, verification and performance check post-maintenance.
- 5. Apply preventive maintenance sticker/tag after successful service. All work are signed and documented.