

# LAMPIRAN - A1

RUJ: BME/A2K/(1654)/2026/HTD (B8 )

11/4/2026

TO REPAIR AND SUPPLY SPARE PARTS FOR TWO (2) UNITS OF ELECTRIC BED, BRAND: HILLROM, MODEL: HR-405 AT WARD 31 WCC RIPAS HOSPITAL.

## SCOPE OF WORK

To repair and supply spare parts for two (2) units of Electric bed, Brand: hillrom, Model: HR-405 at Ward 31 WCC Ripas Hospital. Detail are as follow:

1. BME16641, Brand: Hillrom, Model: HR-405, SN: O244HE5224, at Ward 31 W/order 2026-11365 (Item 1,2,3,4,5,8)
2. BME13808, Brand: Hillrom, Model: HR-405, SN: O246HE3613, at Ward 21, W/order 2025-9456 (Item 1,2,4,5,6,7,8)

- Scope of work to follow equipment manual/recommendation specific for this system which include the following where if necessary:

(i) installation of items listed in spareparts list (Lampiran A2)

(ii) alignment

(iii) calibration

(iv) optimisation

(vi) any other related maintenance works required after installation of items listed in spareparts list (Lampiran A2)

- Perform functional test, verification and performance check post-maintenance.

- Disposal of any used spare parts, unless otherwise instructed.

- Work on the system is to be carried out by engineer(s) authorised in providing maintenance to the equipment.

## LAMPIRAN - A2

RUJ: BME/A2K/(1654)/2026/HTD (B8 )

TO REPAIR AND SUPPLY SPARE PARTS FOR TWO (2) UNITS OF ELECTRIC BED, BRAND: HILLROM, MODEL: HR-405 AT WARD 31 WCC RIPAS HOSPITAL.

	SPAREPART	PART NUMBER	QUANTITY
1	LEFT GUARDRAIL MASK, LATERAL	159394	2
2	RIGHT GUARDRAIL MASK, LATERAL	159392	2
3	SCREW SIDE RAIL BRACKET MOUNT (P1440B)	141133	1
4	RIGHT GUARDRAIL MASK, INSIDE	159391	2
5	LABEL, LEFT GUARDRAIL, INSIDE	159393	2
6	INDIV. BRAKE/STEER CASTER	131434	2
7	INDIV.CASTER,BRAKE	131429	2
8	SERVICE CHARGES		2