

Rujukan Kami: **(86) MOH/HQ/P/IKLAN-SH/2025**

LAMPIRAN 2

BIL	Quotation Reference	Description	Advertisement Date	Closing Date (Not Later Than 09.00AM)	Quotation Fee	Requesting Department
2	BME/A2K/(1442)/2025/HTD (B4)	TO REPAIR 4 UNITS OF HOLTERS BRAND: SCHILLER AT CARDIO CLINIC, RIPAS HOSPITAL.	10/06/2025	05/07/2025	\$5.00	JABATAN TEKNOLOGI PENJAGAAN KESIHATAN, KEMENTERIAN KESIHATAN

LAMPIRAN - A1

RUJ: BME/A2K/(1442)/2025/HTD (B4)

27/5/2025

TO REPAIR 4 UNITS OF HOLTERS BRAND: SCHILLER AT CARDIO CLINIC, RIPAS HOSPITAL

SCOPE OF WORK

- 1) housing part to replace : -
to supply and replace of new housing kit (inclusive of housing upper part with display, housing lower part, battery cover and lock assembly)
a) bme20502 - sn : 350.007754
b) bme20500 - sn : 350.009728
- 2) housing part to replace : -
to supply and replace of new housing kit (inclusive of housing upper part with display, housing lower part, battery cover and lock assembly)
a) - sn : 3040.001441
- 3) LOCK CASING TO REPLACE
to supply and replace of new LOCK CASING
a) bme20499 - sn : 350.009702
- 4) 7 LEAD ECG CABLE
to supply and replace of new 7 LEAD ECG CABLE
a) bme20499 - sn : 350.009702
b) bme20502 - sn : 350.007754
c) bme20500 - sn : 350.009728
- 5) 12 LEAD ECG CABLE
TO SUPPLY AND REPLACE OF NEW 12 LEAD ECG CABLE
a) sn : 3040.001441

TO REPAIR 4 UNITS OF HOLLTERS BRAND: SCHILLER AT CARDIO CLINIC, RIPAS HOSPITAL

	SPAREPART	PART NUMBER	QUANTITY
1	HOUSING KIT FOR AR 12 PLUS		2
2	HOUSING KIT FOR FD12 PLUS		1
3	LOCKING SLOT FOR AR12 PLUS		1
4	7 LEAD ECG CABLE FOR SCHILLER AR 12 PLUS		3
5	12 LEAD ECG CABLE FOR SCHILLER FD12 PLUS		1