

LAMPIRAN - A2

RUJ: BME/A2K/(1586)/2026/HTD (C21)

TO REPAIR FOUR (4) UNIT OF GE HEALTHCARE BABY INCUBATOR, MODEL: GIRAFFE OMNIBED (BME17943, BME16722, BME17956 & BME17955) FOR NICU, SCBU RIPASH

SPAREPART	PART NUMBER	QUANTITY
1 East Lift Rail U Channel Assembly	20744711-001	1
2 Wire Harness Hood Position RoHS	2074886-001	1
3 Kit SVCE PCA Relay ROHS Giraffe	2080429-001	1
4 Inner Wall Hybrid GH	6600-1201-500	2
5 Wire Harness - Warmer Heater	6600-0710-700	1

LAMPIRAN - A1

RUJ: BME/A2K/(1586)/2026/HTD (C21)

20/1/2026

TO REPAIR FOUR (4) UNIT OF GE HEALTHCARE BABY INCUBATOR, MODEL: GIRAFFE OMNIBED (BME17943, BME16722, BME17956 & BME17955) FOR NICU, SCBU RIPASH

SCOPE OF WORK

To repair four (4) unit of Baby Incubator, Brand: GE Healthcare Giraffe Omnibed at NICU, SCBU Ripas Hospital. Detail are as follow:

1. BME17943, SN: HDGU60001, Work order: 2025-10512 (To replace Item 1 and 2)
2. BME16722, SN: HDHT50769, Work order: 2025-10516 (To replace Item 3)
3. BME17956, SN: HDGU60015, Work order: 2025-10514 (To replace Item 4)
4. BME17955, SN: HDGU60014, Work order: 2025-10511 (To replace Item 4 and 5)

- Scope of work to follow equipment manual/recommendation specific for this system which include the following where if necessary:

- (i) installation of items listed in spareparts list (Lampiran A2)
 - (ii) alignment
 - (iii) calibration
 - (iv) optimisation
 - (vi) any other related maintenance works required after installation of items listed in spareparts list (Lampiran A2)
- Perform functional test, verification and performance check post-maintenance.
- Disposal of any used spare parts, unless otherwise instructed.
- Work on the system is to be carried out by engineer(s) authorised in providing maintenance to the equipment