

BIL	Quotation Reference	Description	Advertisement Date	Closing Date (Not Later Than 2.00PM)	Quotation Fee	Requesting Department	Focal Person
2	BME/A2K/(936)2022/HTD (A19)	<p>TO SERVICE AND REPAIR ONE (1) UNIT OF OLYMPUS RHINOLARYNGOSCOPE IMAGING SYSTEM, MODEL: CLV-180, SN: 7113142 AT ORL DEPARTMENT, RIPAS HOSPITAL</p> <p>PLACE OF SUBMISSION: QUOTATION BOX (GROUND FLOOR) MINISTRY OF HEALTH COMMONWEALTH DRIVE. BANDAR SERI BEGAWAN, BB 3910 NEGARA BRUNEI DARUSSALAM</p>	31/10/2022	19/11/2022	\$5.00	JABATAN TEKNOLOGI PENJAGAAN KESIHATAN, KEMENTERIAN KESIHATAN.	<p>MUHD AMIRUL FAZLEEN BIN HAJI KHALIDIN</p> <p>JURUTERA PERUBATAN HAYAT</p> <p>TEL: 2242424 ext 8693 (RIPASH)</p>

LAMPIRAN - A1

RUJ: BME/A2K/(936)/2022/HTD (A19)

27/10/2022

TO SERVICE AND REPAIR ONE (1) UNIT OF OLYMPUS RHINOLARYNGOSCOPE IMAGING SYSTEM , MODEL: CLV-180 , SN: 7113142 AT ORL DEPARTMENT, RIPAS HOSPITAL

SCOPE OF WORK

EQUIPMENT DETAILS:

BRAND: OLYMPUS
MODEL: CLV-180
SERIAL NO.: 7113142

SCOPE OF WORK:

1. DELIVER, SUPPLY & REPLACE SPAREPARTS
2. PERFORM ELECTRICAL SAFETY TEST
3. PERFORM FUNCTIONAL TEST
4. PROVIDE CHECKLIST & SERVICE REPORT TO BOTH USER & BME

LAMPIRAN - A2

RUJ: BME/A2K/(936)/2022/HTD (A19)

TO SERVICE AND REPAIR ONE (1) UNIT OF OLYMPUS RHINOLARYNGOSCOPE IMAGING SYSTEM , MODEL: CLV-180 , SN: 7113142 AT ORL DEPARTMENT, RIPAS HOSPITAL

NO	SPAREPART	PART NUMBER	QUANTITY
1	REAR PANEL 6E		1
2	IGNITER NPFU		1