

BIL	Quotation Reference	Description	Advertisement Date	Closing Date (Not Later Than 02.00PM)	Quotation Fee	Requesting Department	Focal Person
4	BME/A2K / (1376)/2025/HTD (B8)	<p><b>REPAIR FIVE (5) UNITS WARMER BLOWER, BRAND: CINCINNATI SUB-ZERO (CSZ), MODEL: 135- WARMAIR, AT ICU 1, ICU 2 &amp; ICU 3 RIPAS HOSPITAL</b></p> <p>PLACE OF SUBMISSION: QUOTATION BOX (GROUND FLOOR) MINISTRY OF HEALTH COMMONWEALTH DRIVE BANDAR SERI BEGAWAN, BB 3910 NEGARA BRUNEI DARUSSALAM</p>	05/02/2025	22/02/2025	\$5.00	JABATAN TEKNOLOGI PENJAGAAN KESIHATAN, KEMENTERIAN KESIHATAN.	<p>NURAMALIAH BINTI HAJI JAMALUDIN</p> <p>JURUTERA PERUBATAN HAYAT</p> <p>TEL: 2242424 ext. 8693 (RIPASH)</p>

# LAMPIRAN - A1

RUJ: BME/A2K/(1376)/2025/HTD (B8 )

23/1/2025

REPAIR FIVE (5) UNITS OF WARMER BLOWER, BRAND: CINCINNATI SUB-ZERO (CSZ), MODEL: 135-WARMAIR, AT ICU 1, ICU 2 & ICU 3 RIPAS HOSPITAL.

## SCOPE OF WORK

Repair five (5) units of Warmer Blower, Brand: Cincinnati Sub-Zero (CSZ), Model: 135-Warmair, detail are as follow:

1. BME13662, SN; 131-1358314, Workorder no. 2024-4536 at ICU 1 Ripas Hospital
2. BME13653, SN; 131-1358305, Workorder no. 2024-4139 at ICU 1 Ripas Hospital
3. BME13649, SN; 131-1358301, Workorder no. 2024-4272 at ICU 2 Ripas Hospital
4. BME13663, SN; 131-1358315, Workorder no. 2024-4210 at ICU 2 Ripas Hospital
5. BME13659, SN; 131-1358311, Workorder no. 2024-4211 at ICU 3 Ripas Hospital

- Scope of work to follow equipment manual/recommendation specific for this system which include the following where if necessary:

- (i) installation of items listed in spareparts list (Lampiran A2)
- (ii) alignment
- (iii) calibration
- (iv) optimisation
- (vi) any other related maintenance works required after installation of items listed in spareparts list

- Perform functional test, verification and performance check post-maintenance.

- Disposal of any used spare parts, unless otherwise instructed.

- Work on the system is to be carried out by engineer(s) authorised in providing maintenance to the equipment.

## LAMPIRAN - A2

RUJ:

BME/A2K/(1376)/2025/HTD (B8 )

REPAIR FIVE (5) UNITS OF WARMER BLOWER, BRAND: CINCINNATI SUB-ZERO (CSZ), MODEL: 135-WARMAIR, AT ICU 1, ICU 2 & ICU 3 RIPAS HOSPITAL.

	SPAREPART	PART NUMBER	QUANTITY
1	FILTER .02 MICRONS	55508	5
2	BUMPER, RECESSED WITH WASHER	55059	3
3	SCREW, M4 X 16MM FOR 135 WARMAIR	60403	3
4	SERVICE CHARGES		5