

LAMPIRAN - A1

RUJ: BME/A2K/(1490)/2025/HTD (B8)

4/8/2025

TO REPAIR, DELIVERY AND INSTALL SPARE PARTS FOR ONE (1) UNIT OF REVERSE OSMOSIS WATER TREATMENT SYSTEM, BRAND: HD INTEGRA, MODEL: AEROS HD-60, SN: 2026-032. 2026-033, BME19413 AT WARD 17/18 RIPAS HOSPITAL.

SCOPE OF WORK

To repair, delivery and install spare parts for one (1) unit of Reverse Osmosis water treatment system at Ward 17/18 Ripas Hospital. Detail are as follow:

1. BME19413, Brand: HD Integra, Model: Aeros HD-60, SN: 2016-032, 2016-033, Workorder 2025-7869

- Scope of work to follow equipment manual/recommendation specific for this system which include the following where if necessary:

(i) installation of items listed in spareparts list (Lampiran A2)

(ii) alignment

(iii) calibration

(iv) optimisation

(vi) any other related maintenance works required after installation of items listed in spareparts list (Lampiran A2)

- Perform functional test, verification and performance check post-maintenance.

- Disposal of any used spare parts, unless otherwise instructed.

- Work on the system is to be carried out by engineer(s) authorised in providing maintenance to the equipment.

LAMPIRAN - A2

RUJ: BME/A2K/(1490)/2025/HTD (B8)

TO REPAIR, DELIVERY AND INSTALL SPARE PARTS FOR ONE (1) UNIT OF REVERSE OSMOSIS WATER TREATMENT SYSTEM, BRAND: HD INTEGRA, MODEL: AEROS HD-60, SN: 2026-032. 2026-033, BME19413 AT WARD 17/18 RIPAS HOSPITAL.

SPAREPART		PART NUMBER	QUANTITY
1	UV LIGHT COMPLETE SET		2