

LAMPIRAN - A1

RUJ: BME/A2K/(1588)/2026/HTD (A16)

27/1/2026

TO PERFORM PLANNED PREVENTIVE MAINTENANCE (PPM) AND REPAIR WORK FOR FOURTEEN (14) UNITS OF EURONDA AUTOCLAVE AT BERAKAS, GADONG, SG ASAM, SENGKURONG, MUARA, SUNGAI BESAR AND BUNUT HEALTH CENTRES, MINISTRY OF HEALTH

SCOPE OF WORK

TO PERFORM PREVENTIVE MAINTENANCE WORK FOR EURONDA AUTOCLAVE MODEL-E7-24L
TO PERFORM ANY REPAIR NECESSARY REPAIR WORK FOR THE AUTOCLAVE
TO PERFORM TEST RUN AND ANY TEST AFTER PPM AND REPAIR WORK HAVE BEEN DONE

BHC	2025-6747	BME12923	E7
	2025-7491	BME12924	E7
GHC	2025-6733	BME12920	E7
	2025-6734	BME12926	E7
MHC	2025-6786	BME12929	E7
	2025-6784	BME7992	E9MED
	2025-6783	BME20713	E7
SG ASAM HC	2025-6917	BME7991	E9 MED
	2025-6916	BME12932	E7
JPS HC	2025-7295	BME12931	E7
	2025-7296	BME21549	E7
SG BESAR HC	2025-6821	BME8382	E7
	2025-10337	BME12944	E7
JEB HC	2025-6709	BME12930	E7

LAMPIRAN - A2

RUJ: BME/A2K/(1588)/2026/HTD (A16)

TO PERFORM PLANNED PREVENTIVE MAINTENANCE (PPM) AND REPAIR WORK FOR FOURTEEN (14) UNITS OF EURONDA AUTOCLAVE AT BERAKAS, GADONG, SG ASAM, SENGKURONG, MUARA, SUNGAI BESAR AND BUNUT HEALTH CENTRES, MINISTRY OF HEALTH

	SPAREPART	PART NUMBER	QUANTITY
1	BACTERIAL FILTER	815120	
2	SILICON GASKET	815121	
3	WATER FILTER	830468	