

LAMPIRAN - A1

RUJ: BME/A2K/(1602)/2026/HTD (B8)

3/2/2026

TO REPAIR TWO (2) UNITS OF MULTI-PARAMETER PATIENT MONITOR, BRAND: WELCH ALLYN, MODEL: SPOT VITAL SIGNS LXI AT WCC RIPAS HOSPITAL.

SCOPE OF WORK

To repair two (2) units of Multi-parameter patient monitor, Brand: Welch Allyn, Model: Spot vital sign-LXi at WCC Ripas Hospital. Detail are as follow:

1. BME15413, Brand: Welch Allyn, Model: Spot Vital Signs LXI, SN: 20131106804, at Ward 30, W/order 2025-8133 (item 1,2,3,4,5,6)
2. BME15420, Brand: Welch Allyn, Model: Spot Vital Signs LXI, SN: 20131106811, at Ward 30, W/order 2025-8134 (item 1,2,4,5,6)

- Scope of work to follow equipment manual/recommendation specific for this system which include the following where if necessary:

- (i) installation of items listed in spareparts list (Lampiran A2)
- (ii) alignment
- (iii) calibration
- (iv) optimisation
- (v) Top up gas
- (vi) any other related maintenance works required after installation of items listed in spareparts list (Lampiran A2)

- Functional check post-maintenance.

- Disposal of any used spare parts, unless otherwise instructed.

- Work on the system is to be carried out by engineer(s) authorised in providing maintenance to the equipment.

- Vendor(s) to submit maintenance checklist/details/scope specific for the equipment along with other necessary documents to join this tender.

LAMPIRAN - A2

RUJ: BME/A2K/(1602)/2026/HTD (B8)

TO REPAIR TWO (2) UNITS OF MULTI-PARAMETER PATIENT MONITOR, BRAND: WELCH ALLYN, MODEL: SPOT VITAL SIGNS LXI AT WCC RIPAS HOSPITAL.

	SPAREPART	PART NUMBER	QUANTITY
1	POWER SUPPLY WITH BRACKET, SPOT LXI	4500-PS	2
2	FINGER CLIP SPO2 SENSOR, ADULT	DS100A	2
3	PROBE WELL KIT OEM ORAL 9'	02895-000	1
4	LI-ION BATTERY FOR SPOT VITAL SIGNS LXI	105632	2
5	NIBP CUFF ADULT 11, SPOT VITAL SIGNS	REUSE-11-2MQ	2
6	SERVICE CHARGES		2